






**#300** FIXED S.S. HEX BUSHING TOWARDS PROCESS



**#310** FIXED S.S. HEX BUSHING TOWARDS COLD END




**#320** FIXED S.S. HEX NIPPLE




**#321** SPRING LOADED S.S. HEX NIPPLE

**#330** FIXED C.S. NIPPLE




**#331** SPRING LOADED C.S. NIPPLE

**#340** FIXED C.S. NIPPLE AND UNION




**#341** SPRING LOADED C.S. NIPPLE AND UNION

**#350** FIXED C.S. NIPPLE, UNION, NIPPLE




**#351** SPRING LOADED C.S. NIPPLE, UNION, NIPPLE

**#400** SCREW COVER HEAD AND FIXED BUSHING




**#410** SCREW COVER HEAD AND FIXED S.S. HEX NIPPLE




**#411** SCREW COVER HEAD AND SPRING LOADED S.S. HEX NIPPLE

**#420** SCREW COVER HEAD AND FIXED C.S. NIPPLE




**#421** SCREW COVER HEAD AND SPRING LOADED C.S. NIPPLE

**#430** SCREW COVER HEAD AND FIXED C.S. NIPPLE AND UNION



**#431** SCREW COVER HEAD AND SPRING LOADED C.S. NIPPLE AND UNION

**#440** SCREW COVER HEAD AND FIXED C.S. NIPPLE, UNION, NIPPLE



**#441** SCREW COVER HEAD AND SPRING LOADED C.S. NIPPLE, UNION, NIPPLE